


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/6/24 at 6:35:57 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.





Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated
Accident / Damage Damage reported: 02/13/2015.	Minor Damage
Manufacturer Recall No open recalls reported to CARFAX. Check with an authorized Lexus dealer for any open recalls. View Toyota disclosure	No Recalls Reported

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem




GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate


CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2004
Type of owner	Personal
Estimated length of ownership	19 yrs. 6 mo.
Owned in the following states/provinces	California
Estimated miles driven per year	11,410/yr
Last reported odometer reading	215,922

CARFAX Detailed History

Owner 1		0-3	Low mileage! This	ownei	drove less	Personal Vehicle
Date	Mileage	Source			Comments	
07/31/2004		NICB			Vehicle manuf original dealer	factured and shipped to r
08/04/2004		Mission 949-347-southcountiejo.co	untylexusatmissi com	×	Vehicle servic - Pre-delivery in	red nspection completed
08/24/2004		Mission 949-347-southcound onviejo.co	untylexusatmissi com	×	Vehicle servic	ed
10/22/2004	24	Californi Motor Ve Aliso Vie	ehicle Dept.		Title issued or - First owner re - Titled or regis	
11/12/2004		Mission 949-347-southcound onviejo.co	untylexusatmissi com	×	Vehicle service - Recommende performed - Engine check	ed maintenance
11/22/2004		Mission 949-347-southcound onviejo.co	untylexusatmissi com	×	Vehicle servic	ed
11/25/2004			a ehicle Dept. Niguel, CA			r updated updated when owner chicle to a new location

02/28/2005	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews Customer Favorites	×	Vehicle serviced - 5,000 mile service performed
07/13/2005	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews Customer Favorites	×	Vehicle serviced - 10,000 mile service performed
12/06/2005	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews ▼ 10,424 Customer Favorites	*	Vehicle serviced - Oil and filter changed
01/18/2006	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews ▼ 10,424 Customer Favorites	*	Vehicle serviced
05/23/2006	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews Customer Favorites	×	Vehicle serviced - Tire repaired - Tire condition and pressure checked
06/19/2006	South County Lexus Mission Viejo, CA 949-347-3517	×	Vehicle serviced - Tire condition and pressure checked





949-347-3517 southcountylexusatmissi onviejo.com **4.8 / 5.0** 967 Verified Reviews 10,424 Customer Favorites 06/17/2009 South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com **4.8 / 5.0** 967 Verified Reviews 10,424 Customer Favorites 10/28/2009 South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com **4.8 / 5.0** 967 Verified Reviews 10,424 Customer Favorites 03/24/2010 South County Lexus Mission Viejo, CA



Vehicle serviced

- Recommended maintenance performed
- Battery/charging system checked
- Brakes checked
- Oil and filter changed
- Tire(s) balanced
- Tire condition and pressure checked
- Tires rotated



Vehicle serviced

- Recommended maintenance performed
- Maintenance inspection completed
- Rear brake pads replaced
- Drivability/performance checked
- Brakes checked
- Oil and filter changed
- Tires rotated

949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Drivability/performance checked
- Brakes checked
- Fluids checked
- Oil and filter changed
- Tires rotated
- Power steering fluid flushed/changed

06/09/2010

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

- Maintenance inspection completed

06/19/2010

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com





1.8 / 5.0

967 Verified Reviews



Vehicle serviced







107,800 03/27/2013

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com

Favorites

4.8 / 5.0

967 Verified Reviews

10,424 Customer Favorites



Vehicle serviced

- -Tire(s) balanced
- Four tires balanced
- Four tires mounted
- Tire(s) mounted
- Four wheel alignment performed
- Alignment performed

05/09/2013 110,082 South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked
- Air filter replaced

10/29/2013 115,029 South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Tires rotated
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked
- Rear brake pads replaced

03/18/2014 120,114

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



+ 4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

- Recommended maintenance performed
- Maintenance inspection completed
- 120,000 mile service performed
- Transmission fluid changed
- Brake fluid flushed/changed
- Differential fluid flushed/changed
- Rear differential fluid flushed/changed
- Rear differential serviced
- Transmission fluid flushed

08/29/2014

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



Vehicle serviced

- Maintenance inspection completed
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked
- Tires rotated
- Emissions inspection performed

		Customer		
08/29/2014	124,999	California Inspection Station Mission Viejo, CA		Passed emissions inspection
12/01/2014	128,189	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com 4.8 / 5.0 967 Verified Reviews Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Battery serviced - Tire condition and pressure checked
01/16/2015	130,023	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Fuel injection system flushed/serviced
02/13/2015		Damage Report	•	Damage reported: minor damage - Damage to rear
			МІ	Damage Severity Scale MINOR MODERATE SEVERE
		CAR		Damage Location FRONT LEFT RIGHT
	CAR	FAX HAS THE MOS	T	

REAR

ACCIDENT & DAMAGE

INFORMATION



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

05/29/2015 138,609

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Battery/charging system checked
- Alignment checked
- Tire condition and pressure checked
- Drivability/performance checked
- Air filter replaced
- Fluids checked
- Oil and filter changed
- Tires rotated
- Vehicle washed/detailed
- Cabin air filter replaced/cleaned

07/29/2015

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

10/07/2015 139,974 South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



10,424 Customer Favorites



Vehicle serviced

- Rear brakes serviced/adjusted
- Brake pads replaced
- Brake rotor(s) resurfaced
- Brake calipers cleaned/serviced
- Brakes serviced

02/16/2016 145,108

South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



4.8 / 5.0

967 Verified Reviews



+ 4.8 / 5.0

10,424 Customer Favorites



Vehicle serviced

07/08/2016

150,400


South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com



Vehicle serviced

		967 Verified Reviews Customer Favorites		
09/23/2016 1	154,819	California Inspection Station		Passed emissions inspection
09/29/2016 1	155,308	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews ♥ 10,424 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Alignment checked - Tire condition and pressure checked - Fluids checked - Oil and filter changed - Brake fluid flushed/changed
01/19/2017 1	160,207	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com 4.8 / 5.0 967 Verified Reviews 10,424 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Four tires mounted - Four wheel alignment performed - Alignment performed - Battery/charging system checked - Alignment checked - Tire condition and pressure checked - Oil and filter changed - Control arm(s) replaced
02/11/2017 1	161,371	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews ▼ 10,424 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Front wiper blades/refills replaced
05/10/2017	165,354	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com 4.8 / 5.0 967 Verified Reviews 10,424 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Brakes checked - Four tires balanced - Tires rotated - Four wheel alignment performed - Alignment performed - Battery/charging system checked - Alignment checked - Tire condition and pressure checked - Fluids checked - Oil and filter changed
10/03/2017 1	170,228	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com	*	Vehicle serviced - Maintenance inspection completed - Brakes checked - Four tires balanced - Tires rotated

		★ 4.8 / 5.0 967 Verified Reviews ● 10,424 Customer Favorites		- Brakes serviced - Battery/charging system checked - Alignment checked - Tire condition and pressure checked - Fluids checked - Oil and filter changed
02/15/2018	175,219	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews ▼ 10,424 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - 10,000 mile service performed - Brakes checked - Four tires balanced - Tires rotated - Brake pads replaced - Brake calipers cleaned/serviced - Brakes serviced - Brake rotor(s) resurfaced - Battery/charging system checked - Alignment checked - Tire condition and pressure checked - Air filter replaced - Light bulb(s) replaced - Cabin air filter replaced/cleaned
06/26/2018	180,173	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com ★ 4.8 / 5.0 967 Verified Reviews Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - 30,000 mile service performed - Brakes checked - Four tires balanced - Tires rotated - Power steering fluid flushed/changed - Body electrical wiring repaired - Engine serviced - Brake fluid flushed/changed - Differential fluid flushed/changed - Rear differential fluid flushed/changed - Rear differential serviced
10/09/2018	183,520	California Inspection Station		Passed emissions inspection
12/21/2018	185,083	South County Lexus Mission Viejo, CA 949-347-3517 southcountylexusatmissi onviejo.com 4.8 / 5.0 967 Verified Reviews Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Brakes checked - Four tires balanced - Tires rotated
08/21/2019	190,134	South County Lexus Mission Viejo, CA 949-347-3517	*	Vehicle serviced - Maintenance inspection completed - 10,000 mile service performed - Brakes checked



11/29/2021 206,361 Paradise Automotive Vehicle serviced Group San Juan Capistrano, CA 949-347-2522 iparadise.com **+** 4.8 / 5.0 66 Verified Reviews 13 Customer Favorites 02/04/2022 207,433 South County Lexus Vehicle serviced - Maintenance inspection completed Mission Viejo, CA 949-347-3517 - Brakes checked southcountylexusatmissi onviejo.com **4.8 / 5.0** 967 Verified Reviews 10,424 Customer Favorites 03/31/2022 207,722 Lexus of Cerritos Vehicle serviced Cerritos, CA - Maintenance inspection completed 562-263-7857 - Battery/charging system checked - Brakes checked cerritoslexus.com - Engine/powertrain computer/module **4.4 / 5.0** replaced 249 Verified Reviews - Tire condition and pressure checked **335** Customer Favorites 08/17/2022 210,208 Paradise Automotive Vehicle serviced - Oil and filter changed Group San Juan Capistrano, CA - Tires rotated 949-347-2522 - Brakes checked iparadise.com **+ 4.8 / 5.0** 66 Verified Reviews **13** Customer Favorites 09/01/2022 210,347 Paradise Automotive Vehicle serviced - Radiator checked Group - Upper radiator hose replaced San Juan Capistrano, CA 949-347-2522 Radiator hose(s) replaced iparadise.com - Radiator cap replaced **+** 4.8 / 5.0 66 Verified Reviews **13** Customer Favorites 09/30/2022 210,865 Vehicle serviced San Luis Auto Repair & - Emissions inspection performed SMOG San Luis Obispo, CA 805-541-3070

1.9 / 5.0

42 Verified Reviews

		39 Customer Favorites		
09/30/2022		California Inspection Station		Passed emissions inspection
02/07/2023	213,304	Paradise Automotive Group San Juan Capistrano, CA 949-347-2522 jparadise.com	×	Vehicle serviced - Antifreeze/coolant checked
02/28/2023	213,778	Paradise Automotive Group San Juan Capistrano, CA 949-347-2522 jparadise.com 4.8 / 5.0 66 Verified Reviews 13 Customer Favorites	×	Vehicle serviced
09/19/2023	215,922	Paradise Automotive Group San Juan Capistrano, CA 949-347-2522 jparadise.com 4.8 / 5.0 66 Verified Reviews 13 Customer Favorites	×	Vehicle serviced - Oil and filter changed - Drive belts checked
04/25/2024		California Motor Vehicle Dept. Mission Viejo, CA		Title issued or updated - Dealer took title of this vehicle while it was in inventory

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

• This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/6/24 at 6:35:57 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Lexus Recall / Service Campaign

Portions of this report have been included under license from Toyota Motor North America, Inc. ("TOYOTA"), License Agreement TMS1013. This data applies only to vehicle marketed or originally sold in Mexico and the United States of America, including Guam, Saipan, American Samoa, Puerto Rico, the U.S. Virgin Islands and the other United States territories and protectorates with currently open safety or emissions recalls, or service campaigns. While TOYOTA provides data to Carfax Inc. on a regular basis, this report may not include very recent activity. For the manufacturer's most current information on recall/campaign activity for any Toyota, Lexus or Scion brand vehicle, you must go to http://toyota.com/recall or http://lexus.com/recall...

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



C About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved. 5/6/24 6:35:57 PM (CDT)

nave reviewed and received a ehicle (VIN: JTHBN36F3401 5/6/24 at 7:35 PM (EDT).	a copy of the CARFAX 71790), which is base	(Vehicle History Report for this 20 ed on information supplied to CARF	04 LEXUS LS 430 FAX and available as of