

Display CARFAX in online listings:



This report provided free of charge by:

**The Car Connect Auto Group**

13409 Garvey Ave Ste 6  
Baldwin Park, CA 91706

626-649-3598



## Vehicle History Report™

US \$44.99

### 2001 LEXUS LS 430

VIN: JTHBN30F010006025  
SEDAN 4 DR  
4.3L V8 F DOHC  
GASOLINE  
REAR WHEEL DRIVE

This CARFAX Report Provided  
by:

**The Car Connect Auto  
Group**



Damage reported



**62** Service history records



CARFAX 1-Owner vehicle



Personal vehicle



Last owned in California



**229,130** Last reported odometer reading

CARFAX HAS THE MOST  
ACCIDENT & DAMAGE  
INFORMATION



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/30/24 at 2:24:28 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1



05/29/2003

**Vehicle inspected after an accident or other incident**

Event 2

03/15/2007

**Damage reported: minor damage**



<b>CARFAX</b> Additional History Not all accidents / issues are reported to CARFAX	Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> Inspected for damage: 05/29/2003. Damage reported: 03/15/2007.	Damage Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check with an authorized Lexus dealer for any open recalls. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired

<b>CARFAX</b> Title History	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	No Problem

<b>CARFAX</b> Ownership History The number of owners is estimated	Owner 1
Year purchased	2000
Type of owner	Personal





Estimated length of ownership	23 yrs. 11 mo.
Owned in the following states/provinces	California
Estimated miles driven per year	9,639/yr
Last reported odometer reading	229,130

## Detailed History



### Owner 1











Purchased: 2000




**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.





Personal Vehicle  
9,639 mi/yr








Date	Mileage	Source	Comments
10/19/2000		NICB	<b>Vehicle manufactured and shipped to original dealer</b>
10/30/2000	11	California Motor Vehicle Dept. Saratoga, CA	<b>Odometer reading reported</b>
12/15/2000		California Motor Vehicle Dept. Saratoga, CA	<b>Title issued or updated</b> - First owner reported - Titled or registered as personal vehicle
05/29/2003	43,952	Damage Report	<b>Vehicle inspected after an accident or other incident</b> - Damage to rear  <b>A vehicle inspection completed by your dealer or professional inspector is recommended</b>
10/11/2003	50,144	Service Facility	<b>Vehicle serviced</b>
10/11/2003		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com <b>4.6 / 5.0</b> 128 Verified Reviews	<b>Vehicle serviced</b> - Front brake rotor(s) resurfaced - Front brake pads replaced - Brakes checked - Oil and filter changed
01/14/2004	55,262	Service Facility	<b>Vehicle serviced</b> - Recommended maintenance performed - 55,000 mile service performed - Wiper(s) replaced

01/14/2004		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - 55,000 mile service performed - Wiper(s) replaced - Steering/suspension checked
04/16/2004	60,195	Service Facility	 <b>Vehicle serviced</b> - Recommended maintenance performed
08/12/2004	65,732	Service Facility	 <b>Vehicle serviced</b> - Maintenance inspection completed - Recommended maintenance performed
11/06/2004	70,537	Service Facility	 <b>Vehicle serviced</b> - Recommended maintenance performed
11/23/2004	70,631	Service Facility	 <b>Vehicle serviced</b> - Recommended maintenance performed
12/07/2004	71,829	Service Facility	 <b>Vehicle serviced</b> - Brake light bulb(s) replaced
12/27/2004	72,511	Service Facility	 <b>Vehicle serviced</b> - Maintenance inspection completed - Recommended maintenance performed
01/20/2005	73,122	Service Facility	 <b>Vehicle serviced</b>
03/15/2007		Damage Report	 <b>Damage reported: minor damage</b> - Damage to left rear - Damage to rear
<div data-bbox="857 1478 1412 1675" data-label="Figure"> <p style="text-align: center;"><b>Damage Severity Scale</b></p>  <p style="text-align: center;">MINOR                      MODERATE                      SEVERE</p> </div> <div data-bbox="857 1692 1412 2026" data-label="Diagram"> <p style="text-align: center;"><b>Damage Location</b></p> <p style="text-align: center;">FRONT</p> <p style="text-align: center;">LEFT                      RIGHT</p> </div>			



## CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION

08/24/2007	106,434	California Inspection Station		<b>Passed emissions inspection</b>
09/27/2007		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews		<b>Vehicle serviced</b>
11/28/2007		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews		<b>Vehicle serviced</b> - Oil and filter changed
12/14/2007		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews		<b>Vehicle serviced</b> - Light bulb(s) replaced
04/25/2008		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews		<b>Vehicle serviced</b> - 120,000 mile service performed

11/01/2008		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - Oil and filter changed
04/29/2009		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - Oil and filter changed - Tires rotated
09/09/2009	127,875	California Inspection Station Saratoga, CA	<b>Passed emissions inspection</b>
11/09/2009		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - Wiper(s) replaced - Oil and filter changed
11/25/2009		Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - Door check replaced
05/05/2010	134,349	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - Recommended maintenance performed - 135,000 mile service performed - Tire(s) balanced - Tail light bulb(s) replaced - Front brake pads replaced - Brake rotor(s) resurfaced - Rear brake pads replaced
08/14/2010	137,452	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - 30,000 mile service performed - Power steering fluid flushed/changed - Fuel system cleaned/serviced - Transmission fluid changed - Differential fluid flushed/changed - Differential serviced
08/14/2010	137,455	Lexus of Fremont Fremont, CA 510-657-6600 lexusfremont.com	 <b>Vehicle serviced</b> - 30,000 mile service performed - Differential fluid flushed/changed - Differential serviced

★ 4.6 / 5.0  
535 Verified Reviews  
♥ 45 Customer Favorites

- Fuel system cleaned/serviced
- Power steering fluid flushed/changed
- Transmission fluid changed

03/14/2011 142,776 Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com  
★ 4.6 / 5.0  
128 Verified Reviews



- Vehicle serviced**
- Fluids checked
  - Oil and filter changed
  - Tire condition and pressure checked
  - Vehicle washed/detailed
  - Drain plug gasket replaced

03/14/2011 Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com  
★ 4.6 / 5.0  
535 Verified Reviews  
♥ 45 Customer Favorites



- Vehicle serviced**
- Oil and filter changed

05/13/2011 143,968 Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com  
★ 4.6 / 5.0  
128 Verified Reviews



- Vehicle serviced**
- Maintenance inspection completed
  - Battery/charging system checked
  - Lower control arm(s) replaced
  - Four wheel alignment performed

05/13/2011 143,970 Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com  
★ 4.6 / 5.0  
535 Verified Reviews  
♥ 45 Customer Favorites



- Vehicle serviced**
- Maintenance inspection completed
  - Battery/charging system checked
  - Four wheel alignment performed
  - Lower control arm(s) replaced

08/23/2011 146,158 California  
Inspection Station  
San Jose, CA

**Passed emissions inspection**

10/26/2011 147,541 Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com  
★ 4.6 / 5.0  
128 Verified Reviews




- Vehicle serviced**
- Maintenance inspection completed
  - Fluids checked
  - Oil and filter changed
  - Tire condition and pressure checked
  - Vehicle washed/detailed
  - Drain plug gasket replaced
  - Cabin air filter replaced/cleaned

10/26/2011 147,542 Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com  
★ 4.6 / 5.0



- Vehicle serviced**
- Maintenance inspection completed
  - Oil and filter changed
  - Cabin air filter replaced/cleaned

535 Verified Reviews

 45 Customer Favorites

11/21/2012 157,261

Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com

 4.6 / 5.0

128 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Wiper(s) replaced
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked
- Vehicle washed/detailed
- Drain plug gasket replaced

11/21/2012 157,262

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

 4.6 / 5.0

535 Verified Reviews

 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Wiper(s) replaced
- Oil and filter changed

01/30/2013 159,000

Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com

 4.6 / 5.0

128 Verified Reviews



**Vehicle serviced**

01/30/2013 159,001

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

 4.6 / 5.0

535 Verified Reviews

 45 Customer Favorites



**Vehicle serviced**

05/22/2013 162,420

Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com

 4.6 / 5.0

128 Verified Reviews



**Vehicle serviced**


- Maintenance inspection completed
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked
- Vehicle washed/detailed
- Drain plug gasket replaced
- Four wheel alignment performed
- Power steering fluid flushed/changed

05/22/2013

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

 4.6 / 5.0

535 Verified Reviews







 45 Customer Favorites










**Vehicle serviced**

- Maintenance inspection completed
- Oil and filter changed
- Four wheel alignment performed
- Power steering fluid flushed/changed




11/27/2013	167,480	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - 30,000 mile service performed - Wiper(s) replaced - Front brake rotor(s) replaced - Front brake pads replaced - Anti-theft/keyless remote battery replaced
11/27/2013		Lexus of Fremont Fremont, CA 510-657-6600 lexusfremont.com ★ 4.6 / 5.0 535 Verified Reviews ❤️ 45 Customer Favorites	 <b>Vehicle serviced</b> - 30,000 mile service performed - Wiper(s) replaced - Front brake rotor(s) replaced - Front brake pads replaced - Anti-theft/keyless remote battery replaced
12/30/2013	168,238	California Inspection Station San Jose, CA	<b>Passed emissions inspection</b>
07/10/2014	172,276	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - 10,000 mile service performed
07/10/2014		Lexus of Fremont Fremont, CA 510-657-6600 lexusfremont.com ★ 4.6 / 5.0 535 Verified Reviews ❤️ 45 Customer Favorites	 <b>Vehicle serviced</b> - 10,000 mile service performed
03/25/2015	177,210	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews	 <b>Vehicle serviced</b> - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Vehicle washed/detailed - Drain plug gasket replaced - Tires rotated
03/25/2015		Lexus of Fremont Fremont, CA 510-657-6600 lexusfremont.com ★ 4.6 / 5.0 535 Verified Reviews ❤️ 45 Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Tires rotated

09/08/2015	180,977	California Inspection Station		<b>Passed emissions inspection</b>
10/27/2015	181,888	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews		<b>Vehicle serviced</b> - 90,000 mile service performed - Tire(s) balanced - Four tires mounted - Four wheel alignment performed
10/27/2015		Lexus of Fremont Fremont, CA 510-657-6600 lexusfremont.com ★ 4.6 / 5.0 535 Verified Reviews ❤️ 45 Customer Favorites		<b>Vehicle serviced</b> - 90,000 mile service performed - Tire(s) balanced - Four tires mounted - Four wheel alignment performed
04/20/2016	185,611	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews		<b>Vehicle serviced</b> - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Vehicle washed/detailed - Drain plug gasket replaced - Tires rotated
04/20/2016		Lexus of Fremont Fremont, CA 510-657-6600 lexusfremont.com ★ 4.6 / 5.0 535 Verified Reviews ❤️ 45 Customer Favorites		<b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Tires rotated
01/09/2017	191,725	Magnussen Lexus Fremont, CA 510-657-6600 magnussenlexus.com ★ 4.6 / 5.0 128 Verified Reviews		<b>Vehicle serviced</b> - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Vehicle washed/detailed - Drain plug gasket replaced - Battery serviced - Power steering fluid flushed/changed - Tires rotated - Shift lever seal replaced
01/09/2017		Lexus of Fremont Fremont, CA 510-657-6600 lexusfremont.com ★ 4.6 / 5.0 535 Verified Reviews		<b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Battery serviced - Power steering fluid flushed/changed

 45 Customer Favorites



- Tires rotated
- Shift lever seal replaced

09/14/2017 196,642 Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com  
 4.6 / 5.0  
128 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked
- Vehicle washed/detailed
- Drain plug gasket replaced
- Battery serviced
- Tires rotated

09/14/2017  
Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com  
 4.6 / 5.0  
535 Verified Reviews  
 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Battery serviced
- Tires rotated

01/13/2018 199,114 California  
Inspection Station



**Passed emissions inspection**

04/25/2018 200,715 Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com  
 4.6 / 5.0  
128 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Vehicle washed/detailed
- Drain plug gasket replaced
- Battery serviced
- Tires rotated
- Front brake pads replaced
- Brake rotor(s) resurfaced
- Rear brake pads replaced
- Air filter replaced
- Cabin air filter replaced/cleaned

04/25/2018  
Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com  
 4.6 / 5.0  
535 Verified Reviews  
 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Battery serviced
- Tires rotated
- Front brake pads replaced
- Brake rotor(s) resurfaced
- Rear brake pads replaced
- Air filter replaced
- Cabin air filter replaced/cleaned

12/06/2018 205,182 Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed
- Tire condition and pressure checked

★ 4.6 / 5.0  
128 Verified Reviews

- Four wheel alignment performed

12/06/2018

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

★ 4.6 / 5.0  
535 Verified Reviews  
♥ 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed
- Tire condition and pressure checked
- Four wheel alignment performed

05/10/2019 208,184

Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com

★ 4.6 / 5.0  
128 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Four tires balanced
- Four tires mounted
- Four wheel alignment performed

05/10/2019

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

★ 4.6 / 5.0  
535 Verified Reviews  
♥ 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Four tires balanced
- Four tires mounted
- Four wheel alignment performed

10/29/2019 211,869

California  
Inspection Station

**Passed emissions inspection**

11/29/2019 212,589

Magnussen Lexus  
Fremont, CA  
510-657-6600  
magnussenlexus.com

★ 4.6 / 5.0  
128 Verified Reviews



**Vehicle serviced**

- 10,000 mile service performed
- Battery/charging system checked
- Transmission fluid changed
- Fuel system cleaned/serviced
- Differential fluid flushed/changed
- Rear differential fluid flushed/changed
- Rear differential serviced
- Brake fluid flushed/changed
- Transmission fluid flushed

11/29/2019

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

★ 4.6 / 5.0  
535 Verified Reviews  
♥ 45 Customer Favorites



**Vehicle serviced**

- 10,000 mile service performed
- Battery/charging system checked
- Transmission fluid changed
- Fuel system cleaned/serviced
- Differential fluid flushed/changed
- Rear differential fluid flushed/changed
- Rear differential serviced
- Brake fluid flushed/changed
- Transmission fluid flushed

03/09/2020 214,390

Magnussen Lexus  
Fremont, CA



**Vehicle serviced**

- Maintenance inspection completed

510-657-6600  
magnussenlexus.com

★ 4.6 / 5.0

128 Verified Reviews

03/09/2020

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

★ 4.6 / 5.0

535 Verified Reviews

♥ 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed

12/04/2020 216,604

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

★ 4.6 / 5.0

535 Verified Reviews

♥ 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed  
- Engine checked  
- Engine/powertrain computer/module checked  
- Battery replaced  
- Battery/charging system checked  
- Vehicle washed/detailed  
- Oil and filter changed

09/15/2021 218,429

California  
Inspection Station

**Passed emissions inspection**

11/30/2021 218,970

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

★ 4.6 / 5.0

535 Verified Reviews

♥ 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed  
- 10,000 mile service performed  
- Tire condition and pressure checked  
- Vehicle washed/detailed  
- Tires rotated  
- Oil and filter changed  
- Brakes checked

10/15/2022 220,673

Lexus of Fremont  
Fremont, CA  
510-657-6600  
lexusfremont.com

★ 4.6 / 5.0

535 Verified Reviews

♥ 45 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed  
- 10,000 mile service performed  
- Four wheel alignment performed  
- Camshaft seal(s) replaced  
- Camshaft(s) replaced/repared  
- Tire condition and pressure checked  
- Vehicle washed/detailed

09/05/2023 223,887

California  
Inspection Station

**Passed emissions inspection**

09/16/2024 229,130

Ac Smog Test Only  
Baldwin Park, CA  
626-960-7170

★ 5.0 / 5.0

5 Verified Reviews

♥ 1 Customer Favorite



**Vehicle serviced**

- Emissions inspection performed

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/30/24 at 2:24:28 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Lexus Recall / Service Campaign

Portions of this report have been included under license from Toyota Motor North America, Inc. ("TOYOTA"), License Agreement TMS1013. This data applies only to vehicle marketed or originally sold in Mexico and the United States of America, including Guam, Saipan, American Samoa, Puerto Rico, the U.S. Virgin Islands and the other United States territories and protectorates with currently open safety or emissions recalls, or service campaigns. While TOYOTA provides data to Carfax Inc. on a regular basis, this report may not include very recent activity. For the manufacturer's most current information on recall/campaign activity for any Toyota, Lexus or Scion brand vehicle, you must go to <http://toyota.com/recall> or <http://lexus.com/recall>.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)

 [@CARFAXinc](https://twitter.com/CARFAXinc)

 About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2001 LEXUS LS 430 vehicle (VIN: JTHBN30F010006025), which is based on information supplied to CARFAX and available as of 9/30/24 at 3:24 PM (EDT).**

---

**Customer Signature**

**Date**

---

**Dealer Signature**

**Date**